

Sensor Report

Hydrogen Sulfide

SENSOR ID: 5546, Facility: Murphy

Equipment ID: SL052301



Equip. Name: SL052301

SCENTROID
Future of Sensory Technology



Report Date: 2026.08.03 00:00 - 2026.08.10 00:00

Last Calibration: N/A

Report Generated: 2026.08.11



Data Trend Shows No Significant Trend →



● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

good: < 10

moderate: < 20

sensitive: < 50

unhealthy: < 100

very unhealthy: < 200

hazardous: < 300

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Sulfur Dioxide

SENSOR ID: 5549, Facility: Murphy

Equipment ID: SL052301





Equip. Name: SL052301

SCENTROID
Future of Sensory Technology

Report Date: 2026.08.03 00:00 - 2026.08.10 00:00

Last Calibration: N/A

Report Generated: 2026.08.11



● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

good: < 35

moderate: < 75

sensitive: < 185

unhealthy: < 304

very unhealthy: < 604

hazardous: < 1004

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Total VOC - PID

SENSOR ID: 5556, Facility: Murphy

Equipment ID: SL052301



Equip. Name: SL052301

SCENTROID
Future of Sensory Technology



Report Date: 2026.08.03 00:00 - 2026.08.10 00:00

Last Calibration: 2023.08.08

Report Generated: 2026.08.11



Data Trend Shows No Significant Trend →



AQI

● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

good: < 50

moderate: < 100

sensitive: < 150

unhealthy: < 200

very unhealthy: < 300

hazardous: < 500

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Sound Intensity Level - Class II

SENSOR ID: 5594, Facility: Murphy

Equipment ID: SL052301




Equip. Name: SL052301



Report Date: 2026.08.03 00:00 - 2026.08.10 00:00

Last Calibration: N/A

Report Generated: 2026.08.11



Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Hydrogen Sulfide

SENSOR ID: 5559, Facility: Murphy

Equipment ID: SL052302



Equip. Name: SL052302

SCENTROID
Future of Sensory Technology



Report Date: 2026.08.03 00:00 - 2026.08.10 00:00

Last Calibration: N/A

Report Generated: 2026.08.11



Data Trend Shows No Significant Trend →



AQI

● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

good: < 10

moderate: < 20

sensitive: < 50

unhealthy: < 100

very unhealthy: < 200

hazardous: < 300

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Sulfur Dioxide

SENSOR ID: 5562, Facility: Murphy

Equipment ID: SL052302



Equip. Name: SL052302

SCENTROID
Future of Sensory Technology



Report Date: 2026.08.03 00:00 - 2026.08.10 00:00

Last Calibration: N/A

Report Generated: 2026.08.11



Data Trend Shows No Significant Trend →



● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

good: < 35

moderate: < 75

sensitive: < 185

unhealthy: < 304

very unhealthy: < 604

hazardous: < 1004

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Total VOC - PID

SENSOR ID: 5569, Facility: Murphy

Equipment ID: SL052302



Equip. Name: SL052302

SCENTROID
Future of Sensory Technology



Report Date: 2026.08.03 00:00 - 2026.08.10 00:00

Last Calibration: 2023.08.08

Report Generated: 2026.08.11



Data Trend Shows No Significant Trend →



● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

good: < 50

moderate: < 100

sensitive: < 150

unhealthy: < 200

very unhealthy: < 300

hazardous: < 500

Connected Events

Date & Time

Type

Notes

Justification

Occurrences

Sensor Report

Sound Intensity Level - Class II

SENSOR ID: 5595, Facility: Murphy

Equipment ID: SL052302





Equip. Name: SL052302


Report Date: 2026.08.03 00:00 - 2026.08.10 00:00

Last Calibration: N/A

Report Generated: 2026.08.11



Data Trend Shows No Significant Trend →



Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------