

Sensor Report
Hydrogen Sulfide
SENSOR ID: 5546, Facility: Murphy



Equipment ID: SL052301
Equip. Name: SL052301

SCENTROID
Future of Sensory Technology



Report Date: 2025.09.01 00:00 – 2025.09.08 00:00

Last Calibration: N/A

Report Generated: 2025.09.09



Data Trend Shows No Significant Trend →



● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Sulfur Dioxide

SENSOR ID: 5549, Facility: Murphy

Equipment ID: SL052301

Equip. Name: SL052301



SCENTROID

Future of Sensory Technology



Report Date: 2025.09.01 00:00 - 2025.09.08 00:00

Last Calibration: N/A

Report Generated: 2025.09.09



Data Trend Shows No Significant Trend →



AQI

● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Total VOC - PID

SENSOR ID: 5556, Facility: Murphy

Equipment ID: SL052301

Equip. Name: SL052301



SCENTROID

Future of Sensory Technology



Report Date: 2025.09.01 00:00 - 2025.09.08 00:00

Last Calibration: 2023.08.08

Report Generated: 2025.09.09



Data Trend Shows No Significant Trend →



AQI

● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time

Type

Notes

Justification

Occurrences

Sensor Report

Sound Intensity Level - Class II

SENSOR ID: 5594, Facility: Murphy

Equipment ID: SL052301

SCENTROID



Future of Sensory Technology

Equip. Name: SL052301


Report Date: 2025.09.01 00:00 - 2025.09.08 00:00

Last Calibration: N/A

Report Generated: 2025.09.09



Data Trend Shows No Significant Trend →



Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Hydrogen Sulfide

SENSOR ID: 5559, Facility: Murphy

Equipment ID: SL052302

Equip. Name: SL052302



SCENTROID

Future of Sensory Technology




Report Date: 2025.09.01 00:00 - 2025.09.08 00:00

Last Calibration: N/A

Report Generated: 2025.09.09



Data Trend Shows No Significant Trend →



AQI

● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time

Type

Notes

Justification

Occurrences

Sensor Report

Sulfur Dioxide

SENSOR ID: 5562, Facility: Murphy

Equipment ID: SL052302

Equip. Name: SL052302



SCENTROID

Future of Sensory Technology



Report Date: 2025.09.01 00:00 - 2025.09.08 00:00

Last Calibration: N/A

Report Generated: 2025.09.09



Data Trend Shows No Significant Trend →



AQI

● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------

Sensor Report

Total VOC - PID

SENSOR ID: 5569, Facility: Murphy

Equipment ID: SL052302

Equip. Name: SL052302



SCENTROID

Future of Sensory Technology



Report Date: 2025,09,01 00:00 - 2025,09,08 00:00

Last Calibration: 2023,08,08

Report Generated: 2025,09,09



Data Trend Shows No Significant Trend →



● good ● moderate ● sensitive ● unhealthy
● very unhealthy ● hazardous

Exceedances

0

Exceeded Time

0%

Alarm Condition

N/A

Connected Events

Date & Time

Type

Notes

Justification

Occurrences

Sensor Report
Sound Intensity Level - Class II
SENSOR ID: 5595, Facility: Murphy



Equipment ID: SL052302
Equip. Name: SL052302




Report Date: 2025.09.01 00:00 - 2025.09.08 00:00

Last Calibration: N/A

Report Generated: 2025.09.09



Data Trend Shows No Significant Trend →



Exceedances
0
Exceeded Time
0%
Alarm Condition
N/A

Connected Events

Date & Time	Type	Notes	Justification	Occurrences
-------------	------	-------	---------------	-------------